




Color Indicator	Specific Gravity	Charge Status
Red	1.100-1.205	Discharged
White	1.205-1.260	Low Charge
Green	1.260-1.300	Fully Charged

TOLERANCE: UNLESS SPECIFIED: .XXXX = +/- .0001 .XXX = +/- .001 .XX = +/- .01 1/X = +/- 1/32 Angles = +/- .5 DEGREE ELECTRONIC DRAWING DO NOT SCALE		MATERIAL AND TREATMENT FINISH QUOTE#		FRANKSVILLE, WI 53126 U.S.A. The information contained in this drawing is the sole property of QuickCable. Any reproduction in part or whole without the written permission of QuickCable, Inc is prohibited.	
DRAWN BY: Josh E		DATE: 8/21/26		TITLE: 120149-2001 Hydrometer	
CHECKED:		SIZE: B		DWG: 120149-2001	
MACHINE:				SHEET 1 of 1	