QUICKCABLE

Material Safety Data Sheet (MSDS)

Description: Heat Shrink Tubing Part Numbe	r: 5611-5619, 5657-5673, 506701-506714
SECTION I CONTACT INFORMATION	
Date: 07/2013 Quick Cable Corporation	
3700 Quick Cable Drive, Franksville, WI 53126 Telephone : 1-800-558-8667	
Emergency Telephone: INFOTRAC 1-800-535-5053	Quick Cable Product I.D.: 5611-5616, 5657-6671
SECTION II HAZARDOUS INGREDIENTS	
*This product is a manufactured article and, as such, is exempt from the hazardous products act. **Overheating to temperatures above 200°C for long periods of time may cause the release of irritating and toxic fumes.	
SECTION III PHYSICAL/CHEMICAL CHARACTERISTICS	
Physical State: Solid Odor and Appearance: Plastic tube, almost odorless, with adhesive lining	Freezing Point: N/A Melting Point: N/A pH: N/A
Odor Threshold (ppm): N/A Vapor Pressure (mmHg): N/A	Specific Gravity (H2O=1): 1.3405 Coefficient: N/A
Vapor Density (air=1): N/A Evaporation Rate: N/A Boiling Point: N/A	Oil Distribution: N/A Solubility in Water: Insoluble
SECTION IV	
FIRE AND EXPLOSION HAZARD DATA	
Flammability Class: N/A LFL: N/A Extinguishing Media: Water spray, Dry chemical, Foam, Carbon Dioxide UFL: N/A Flash Point: N/A UFL: N/A	
SECTION V REACTIVITY DATA	
Stability: Stable	
Conditions to Avoid: Decomposes at elevated temperatures Hazardous Decomposition Products: May produce oxides of carbon, sulphur, nitrogen, acetic acid, antimony and hydrogen halides, acid aldehydes, & vinyl acetate	
Hazardous Polymerization: None Incompatibility: Strong oxidizers	
SECTION VI	
HEALTH HAZARD DATA	
Primary Routes of Exposure: None	Irritancy of Material: Mild
Skin Contact: No unusual dermatitis hazard expected. Hot adhesive can Skin Absorption: None	Carcinogenicity of Material: No
Eye Contact: Mechanical Irritation	Reproductive Effects: No
Inhalation: None	Teratogenicity: No
Ingestion: Low toxicity expected Effects of Acute Exposure: See Above	Mutagenicity: No Synargistic Materials: No
Effects of Chronic Exposure: None Known	Synergistic Materials: No
First Aid Procedures: Eyes: Flush with water for 5 minutes; Skin: In the event of a burn with hot adhesive, immerse the affected part	
in clean, cold, water and seek medical attention. Do not pull off adhesive; Inhalation: If exposed to fumes/gases from overheating, or	
burning, remove to fresh air and seek medical advice; Ingestion: Low toxicity expected.	

SECTION VII PRECAUTIONS FOR SAFE HANDLING AND USE

Spill Procedures: Not Applicable

Waste disposal Method: Do not incinerate, landfill or incinerate in compliance with all federal, provincial, and local regulations **Handling Procedures and Equipment:** Avoid overheating materials above decomposition temperatures. Do not breath fumes produced

during overheating or burning.

Storage Needs: Cool dry environment

Special Shipping Instructions: Not Regulated



Protective Gloves: Wear gloves to protect from thermal burns

Respiratory Protection: Not required with adequate general ventilation

Eye Protection: Safety glasses during flame heating

Footwear: None

Clothing: Fire retardant clothing is recommended

Ventilation Type: General ventilation is adequate

Engineering Controls: General ventilation should be adequate. Use of local ventilation may be required where overheating is expected

SECTION IX

OTHER REGULATORY INFORMATION

This information is accurate to the best of Quick Cable Corporation's knowledge or obtained from sources believed by Quick Cable to be accurate. Before using this product, read all warnings and directions on the label.